



J0
Remote A




Aansluiting op input 1 van de OnAirLight box

Aansluiting op input 2 van de OnAirLight box



Port 1 OnAirLight Box

T = Input 1
R = Input 2
S = shield



Port 2 OnAirLight Box

T = Input 3
R = Input 4
S = shield

OnAirLight

Sheet: /

File: AH_XB_series_Connection.kicad_sch

Title: OnAirLight connection diagram Allan&Heath XB series Mixers

Size: A4

Date:

Rev:

KiCad E.D.A. eeschema (6.0.9)

Id: 1/1